

Grayhill Incorporated

EZCom-LP 900 MHz Digital Radio

FCC ID#: NMAEZCOMLPP

Email Response Response to FCC Email dated June 10, 2003 Correspondence Number: 25285 for Item 4

Please refer to Page 1-4 of the supplied Operators Guide.
Figure 1.3-3 features an operator wearing the OCU Control Unit.

This photo defines the only method of wearing the OCU Control Unit.

This vest is a "break-away" and is critical to operation. It is a light plastic material and orange in color. If caught on anything the vest will tear away from the operator to prevent being dragged or knocked off their feet by a moving locomotive. This vest is only for physical safety. The material of this vest is not designed for or provides for any level of RF "insulation".