



Open area setup

Below 30 MHz



- 1: Equipment Under Test
- 2: Measurement antenna
- 3: Measurement equipment

Between 30 MHz and 1 GHz



- 1: Equipment Under Test
- 2: Measurement antenna
- 3: Measurement equipment

Installation of Equipment Under Test

Open Area Test Site in Position 1 with battery



Open Area Test Site in Position 2 with battery



Open Area Test Site in Position 3 with battery



Open Area Test Site in Position 1 with AC adapter



Open Area Test Site in Position 2 with AC adapter



Open Area Test Site in Position 3 with AC adapter



Open area test site

Measure below 30 MHz



Measure between 30 MHz to 200 MHz



Measure between 200 MHz to 1000 MHz



Conducted measurement setup

AC Conducted Setup with integral antenna



AC Conducted Setup with 50 ohms load

