

INTERTEK TESTING SERVICES

EXHIBIT 5

PRODUCT LABELLING

INTERTEK TESTING SERVICES

5.0 **Product Labelling**

The FCC ID label and label location are attached.

INTERTEK TESTING SERVICES

5.1 Label Artwork

Figure 5.1 FCC ID Label

An engineering drawing of the label which will be permanently affixed to the unit is shown below.

This label will be attached to the unit at the location shown in Exhibit 5.2.



IC NO: XXXXXXXXXX
FCC ID: NS3661R
MADE IN CHINA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

551-6610_-000



Chime Unit



IC NO: XXXXXXXXXX
FCC ID: NS3661T
MADE IN CHINA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

551-6610_-000




Push Button Unit

INTERTEK TESTING SERVICES

5.2 Label Location

Figure 5.2 Label Location

Flat 19, 5/F., Sun Fung Centre, 88 Kwok Shui Road, Kwai Chung, New Territories, Hong Kong.
 TEL.: (852) 2480-1886 FAX.: (852) 2427-4666




FCC ID = NS3661R

HomeSafe

FCC ID: NS3661R
MADE IN CHINA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

ELECTROTECHNICAL				
Incoming Date: 26 Mar 98				
				Kenneth



FCC ID = NS3661T

HomeSafe

FCC ID: NS3661T
MADE IN CHINA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

To: I. T. S.

Attn: Mr. Kenneth Lam.

From: Candy Ng.

(LELUX)