



5. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (Y ORIENTATION, WORST CASE)



RADIATED RF MEASUREMENT SETUP (X ORIENTATION)




RADIATED RF MEASUREMENT SETUP (Z ORIENTATION)




RADIATED RF MEASUREMENT SETUP ON OATS

LOW AND HIGH CHANNELS, WJM3000
LOW, MID, AND HIGH CHANNELS, WJM1000



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



END OF REPORT