



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

April 3, 2002

RE:

FCC ID:

I have a few comments on this Application.

The 731 form you filed has an incorrect FCC ID number for the device. All documentation states the FCC ID should be O6YUTS-EA7T56B, however, the 731 form lists the FCC ID as O6YEA7T56B. Please correct and upload a revised 731 form. As soon as this is done the grant can be issued.

Also, please be aware that while the FCC has in the past allowed extensions of frequency range for licensed devices, it is not clear if this will be allowed by a TCB. While I do not expect a problem, I have asked the FCC for its interpretation on this issue.

A handwritten signature in black ink that reads "Dennis Ward".

Dennis Ward  
Dt Associates  
PO Box 1644  
Mariposa, CA 95338  
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.