



Intertek Testing Services

ETL SEMKO

Report No.: 0205399

Tested By: Hong, Report No.: 0205399


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0205399

Tested By: Hong, Report No.: 0205399

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement
Results:

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

0.53000	32.8	48.0
0.70500	31.6	48.0
0.88000	30.7	48.0
1.14500	29.6	48.0
1.50000	31.2	48.0
1.67500	32.0	48.0
2.82000	33.8	48.0
2.99500	32.9	48.0
3.79000	32.5	48.0
5.46500	34.7	48.0
6.70000	31.8	48.0
8.64000	33.1	48.0
13.39500	30.2	48.0
14.36500	31.6	48.0
17.98000	28.2	48.0

* limit
exceeded

Ctrl No.: N/A