




11AC80MIMO_Ant2_5985




11AC80MIMO_Ant1_6145




11AC80MIMO_Ant2_6145




11AC80MIMO_Ant1_6385




11AC80MIMO_Ant2_6385




11AC80MIMO_Ant1_6465




11AC80MIMO_Ant2_6465




11AC80MIMO_Ant1_6545




11AC80MIMO_Ant2_6545




11AC80MIMO_Ant1_6625




11AC80MIMO_Ant2_6625




11AC80MIMO_Ant1_6705




11AC80MIMO_Ant2_6705




11AC80MIMO_Ant1_6785




11AC80MIMO_Ant2_6785




11AC80MIMO_Ant1_6865




11AC80MIMO_Ant2_6865



11AC80MIMO_Ant1_6945




11AC80MIMO_Ant2_6945




07:17:16 30.07.2024

11AC80MIMO_Ant1_7025




07:20:31 30.07.2024

11AC80MIMO_Ant2_7025




07:22:52 30.07.2024


11AC160MIMO_Ant1_6025




11AC160MIMO_Ant2_6025




11AC160MIMO_Ant1_6185




11AC160MIMO_Ant2_6185




11AC160MIMO_Ant1_6345




11AC160MIMO_Ant2_6345




11AC160MIMO_Ant1_6505




11AC160MIMO_Ant2_6505




11AC160MIMO_Ant1_6665




11AC160MIMO_Ant2_6665




11AC160MIMO_Ant1_6825



11AC160MIMO_Ant2_6825




11AC160MIMO_Ant1_6985




07:57:35 30.07.2024

11AC160MIMO_Ant2_6985




07:59:56 30.07.2024

11AX20MIMO_Ant1_5955




08:03:18 30.07.2024


11AX20MIMO_Ant2_5955




11AX20MIMO_Ant1_6175




11AX20MIMO_Ant2_6175




11AX20MIMO_Ant1_6415




11AX20MIMO_Ant2_6415




11AX20MIMO_Ant1_6435




11AX20MIMO_Ant2_6435




11AX20MIMO_Ant1_6475




11AX20MIMO_Ant2_6475




11AX20MIMO_Ant1_6515




11AX20MIMO_Ant2_6515




11AX20MIMO_Ant1_6535




11AX20MIMO_Ant2_6535




11AX20MIMO_Ant1_6695




11AX20MIMO_Ant2_6695




11AX20MIMO_Ant1_6855




11AX20MIMO_Ant2_6855




11AX20MIMO_Ant1_6875




11AX20MIMO_Ant2_6875




11AX20MIMO_Ant1_6895




11AX20MIMO_Ant2_6895




11AX20MIMO_Ant1_6995




11AX20MIMO_Ant2_6995




11AX20MIMO_Ant1_7115




11AX20MIMO_Ant2_7115




11AX40MIMO_Ant1_5965




11AX40MIMO_Ant2_5965




11AX40MIMO_Ant1_6165




11AX40MIMO_Ant2_6165




11AX40MIMO_Ant1_6405




11AX40MIMO_Ant2_6405




11AX40MIMO_Ant1_6445




11AX40MIMO_Ant2_6445




11AX40MIMO_Ant1_6485




11AX40MIMO_Ant2_6485




11AX40MIMO_Ant1_6525




11AX40MIMO_Ant2_6525




11AX40MIMO_Ant1_6565




11AX40MIMO_Ant2_6565




11AX40MIMO_Ant1_6685




11AX40MIMO_Ant2_6685




11AX40MIMO_Ant1_6845




11AX40MIMO_Ant2_6845




11AX40MIMO_Ant1_6885




11AX40MIMO_Ant2_6885




11AX40MIMO_Ant1_6925




11AX40MIMO_Ant2_6925




11AX40MIMO_Ant1_6965




11AX40MIMO_Ant2_6965



11AX40MIMO_Ant1_7085




11AX40MIMO_Ant2_7085




10:55:41 30.07.2024

11AX80MIMO_Ant1_5985




10:58:47 30.07.2024

11AX80MIMO_Ant2_5985




11:01:07 30.07.2024


11AX80MIMO_Ant1_6145




11AX80MIMO_Ant2_6145




11AX80MIMO_Ant1_6385




11AX80MIMO_Ant2_6385




11AX80MIMO_Ant1_6465




11AX80MIMO_Ant2_6465




11AX80MIMO_Ant1_6545




11AX80MIMO_Ant2_6545




11AX80MIMO_Ant1_6625




11AX80MIMO_Ant2_6625




11AX80MIMO_Ant1_6705




11AX80MIMO_Ant2_6705




11AX80MIMO_Ant1_6785




11AX80MIMO_Ant2_6785




11AX80MIMO_Ant1_6865




11AX80MIMO_Ant2_6865




11AX80MIMO_Ant1_6945




11AX80MIMO_Ant2_6945




11AX80MIMO_Ant1_7025




11AX80MIMO_Ant2_7025




11AX160MIMO_Ant1_6025



11AX160MIMO_Ant2_6025




11AX160MIMO_Ant1_6185




11AX160MIMO_Ant2_6185




11AX160MIMO_Ant1_6345




11AX160MIMO_Ant2_6345




11AX160MIMO_Ant1_6505




11AX160MIMO_Ant2_6505




11AX160MIMO_Ant1_6665




11AX160MIMO_Ant2_6665




11AX160MIMO_Ant1_6825




11AX160MIMO_Ant2_6825




11AX160MIMO_Ant1_6985





Partial RU modes:
All of the configurations or modes are tested, the data of the worst case is recorded in the report.





11AX20MIMO_Ant1_5955_106Tone_RU53



11AX20MIMO_Ant2_5955_26Tone_RU0



03:32:13 03.08.2024

11AX20MIMO_Ant2_5955_52Tone_RU37




03:33:06 03.08.2024

11AX20MIMO_Ant2_5955_106Tone_RU53



11AX20MIMO_Ant1_6175_26Tone_RU0



11AX20MIMO_Ant1_6175_52Tone_RU37



11AX20MIMO_Ant1_6175_106Tone_RU53



11AX20MIMO_Ant2_6175_26Tone_RU0




11AX20MIMO_Ant2_6175_52Tone_RU37



11AX20MIMO_Ant2_6175_106Tone_RU53



11AX20MIMO_Ant1_6415_26Tone_RU0




11AX20MIMO_Ant1_6415_52Tone_RU37



11AX20MIMO_Ant1_6415_106Tone_RU53



11AX20MIMO_Ant2_6415_26Tone_RU0




11AX20MIMO_Ant2_6415_52Tone_RU37




11AX20MIMO_Ant2_6415_106Tone_RU53




11AX20MIMO_Ant1_6435_26Tone_RU0




11AX20MIMO_Ant1_6435_52Tone_RU37



11AX20MIMO_Ant1_6435_106Tone_RU53



11AX20MIMO_Ant2_6435_26Tone_RU0




11AX20MIMO_Ant2_6435_52Tone_RU37




11AX20MIMO_Ant2_6435_106Tone_RU53



11AX20MIMO_Ant1_6475_26Tone_RU0




11AX20MIMO_Ant1_6475_52Tone_RU37



11AX20MIMO_Ant1_6475_106Tone_RU53




11AX20MIMO_Ant2_6475_26Tone_RU0




06:49:20 03.08.2024

11AX20MIMO_Ant2_6475_52Tone_RU37




06:52:15 03.08.2024

11AX20MIMO_Ant2_6475_106Tone_RU53




11AX20MIMO_Ant1_6515_26Tone_RU0




11AX20MIMO_Ant1_6515_52Tone_RU37



11AX20MIMO_Ant1_6515_106Tone_RU53



11AX20MIMO_Ant2_6515_26Tone_RU0




11AX20MIMO_Ant2_6515_52Tone_RU37



11AX20MIMO_Ant2_6515_106Tone_RU53



11AX20MIMO_Ant1_6535_26Tone_RU0



11AX20MIMO_Ant1_6535_52Tone_RU37



11AX20MIMO_Ant1_6535_106Tone_RU53



11AX20MIMO_Ant2_6535_26Tone_RU0



11AX20MIMO_Ant2_6535_52Tone_RU37



11AX20MIMO_Ant2_6535_106Tone_RU53