

APPENDIX 3: Photographs of test setup

Radiated emission (1/2)


Module (Type 1) + Sleeve Antenna
Front




Module (Type 1) + PCB Antenna
Front




Rear (below 1GHz)




Rear (below 1GHz)



Rear (above 1GHz)



Rear (above 1GHz)



UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Radiated emission (2/2)


Module (Type 1) + Wire Antenna
Front




Module (Type 2) + PCB trace Antenna
Front




Rear (below 1GHz)




Rear (below 1GHz)



Rear (above 1GHz)



Rear (above 1GHz)



UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400


Facsimile : +81 463 50 6401

Pre-check of the worst position (1/2)

Dipole Antenna
X-axis




Y-axis




PCB Antenna
X-axis



Y-axis



Z-axis



UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401


Pre-check of the worst position (2/2)

Wire Antenna


X-axis




Y-axis




Module (Type 1),
Module (Type 2) + PCB Antenna
X-axis



Y-axis



Z-axis



END OF REPORT

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401