



Ericsson Wireless Communications, Inc  
6455 Lusk Blvd.  
San Diego, CA 92121-2779

Ph: (858) 332-6026  
FAX: (858) 332-7388  
E-mail: D.Kimball@ericsson.com

|                                  |                                  |
|----------------------------------|----------------------------------|
| Re:                              | FCC ID OJYKAG3                   |
| Applicant:                       | Ericsson Wireless Communications |
| Correspondence Reference Number: | 7891                             |
| 731 Confirmation Number:         | EA94212                          |
| Date of Original E-Mail:         | 05/21/1999                       |

June 8, 2001

Federal Communications Commission  
OET Laboratory Division Electronic Filing Site  
<<https://gulfoss.fcc.gov/prod/oet/index.html>>

Dear Sir or Madam:

Qualcomm, Inc. Wireless Infrastructure Division was purchased by Ericsson Wireless Communications, Inc. effective May 24, 1999. I was Qualcomm's infrastructure regulatory manager and I have transferred to Ericsson. We are requesting a change in the FCC ID for the former Qualcomm 800MHz and 1900MHz base stations and pilot beacons. The 3 character prefix is being changed from J9C (Qualcomm) to OJY (Ericsson).

This request is for FCC ID OJYKAG3, an 800MHz outdoor cellular pilot beacon. The design of the base stations and pilot beacons are unchanged. In addition, the manufacturing location, equipment, processes, and personal remain unchanged. However, we will be changing the branding, trade dress, and model numbers to Ericsson's corporate standards.

The following exhibits are attached, and a separate electronic submission will be made for each FCC ID.

Exhibit 1: FCC ID Change Matrix  
Exhibit 2: FCC ID Label  
Exhibit 3: Photograph showing location of FCC ID label  
Exhibit 4: Front View of Pilot Beacon

Sincerely,

Donald F. Kimball  
Regulatory Senior Staff Engineer/Manager

Exhibit 1: FCC ID Change Matrix

| Qualcomm Model Number | Qualcomm FCC ID | Original Grant Date | Ericsson Model Number | Ericsson FCC ID | FCC Application No. |
|-----------------------|-----------------|---------------------|-----------------------|-----------------|---------------------|
| Base Stations         |                 |                     |                       |                 |                     |
| QCell 2508i           | J9CJAY1         | 07/10/96            | RBS 1102 800          | OJYJAY1         | EA94134             |
| QCell 2519e           | J9CJAY2         | 03/03/98            | RBS 1102 1900         | OJYJAY2         | EA94122             |
| QCell 3508i           | J9CDFK2         | 02/11/98            | RBS 1103 800          | OJYDFK2         | EA94206             |
| QCell 3519i           | J9CDFK1         | 06/02/98            | RBS 1103 1900         | OJYDFK1         | EA94207             |
| QCell 619e            | J9CKAG4         | 04/20/99            | RBS 1106 1900         | OJYKAG4         | EA94209             |
| Pilot Beacons         |                 |                     |                       |                 |                     |
| QCPB 800i             | J9CKAG1         | 04/07/97            | CMS 11 800i           | OJYKAG1         | EA94210             |
| QCPB 1900e            | J9CKAG2         | 08/01/97            | CMS 11 1900e          | OJYKAG2         | EA94211             |
| QCPB 800e             | J9CKAG3         | 01/21/98            | CMS 11 800e           | OJYKAG3         | EA94212             |

Attached under Separate Exhibit Type

**Exhibit 2 FCC ID Label, OJYKAG3**

Attached under Separate Exhibit Type

**Exhibit 3 FCC ID Label Location, OJYKAG3**

Attached under Separate Exhibit Type

**Exhibit 4 Front View, OJYKAG3**