



# Intertek Testing Services

## ETL SEMKO

Report No.: 0103473  
Mode: Talk

Tested By: Hong, Report No.: 0103473


### Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |       |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |



PAGE 1

Ctrl No.: N/A



# Intertek Testing Services

## ETL SEMKO

Report No.: 0103473  
Mode: Talk

Tested By: Hong, Report No.: 0103473

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement

no Results

Ctrl No.: N/A