



Intertek Testing Services

ETL SEMKO

Report No.: 01073251
Mode: Talk

Tested By: Hong, Report No.: 01073251

Scan Settings (1 Range)


Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 18
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698

dBuV



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 01073251
Mode: Talk

Tested By: Hong, Report No.: 01073251

Scan Settings (1 Range)

----- Frequencies ----- || ----- Receiver Settings ----- |

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A