




360 Herndon Park way
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

21 LABEL INFORMATION

21.1 FCC ID LABEL



21.2 WARNING STATEMENT

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.

FCC LABEL AND LOCATION OF LABEL ON EUT

See following pages



360 Herndon Park way
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


FCC LABEL AND LOCATION OF LABEL ON EUT

Tellumat

Model: PLESSEY MDR5800

FCC ID: ONJ-MDR5800ET

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation





360 Herndon Park way
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

FCC LABEL AND LOCATION OF LABEL ON EUT

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation

