



**Exhibit 9: Internal Photographs**



Inside view of 2MOD-6322-A411



Component side of the board (with RF cans installed)




Component side of the board (with RF cans removed)

COMMUNICATION CERTIFICATION LABORATORY

TEST REPORT: 73-7209

FCC ID: OPQ2MOD-6322

Page 52 of 89



Solder side of board

Exhibit 9