

8. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION


X-AXIS PHOTO



Y-AXIS PHOTO




Z-AXIS PHOTO



X-AXIS WITH HEADSET



X-AXIS WITH AC ADAPTER



X-AXIS WITH HEADSET AC ADAPTER



END OF REPORT