



TOMY (Hong Kong) Ltd.
Shenzhen Office

Block B, 11/F Wenjindu Customs Declaration Building, 6 South Dongmen Road, Shenzhen, China.

Tel: (86) 755-228 7149

Fax: (86) 755-228 7143

E-mail : rocky@tomy.com.hk

TO : CMA
ATTN : Mr. Danny Chui
FROM : Rocky Wong
CC : Marty Ching, K. So

DATE : Dec 10, 2001

REF NO. :

TOTAL PAGE (S) 1 OF 1

RE: Letter of class II permissive change

Please refer to following list for changed components in Char-G.

27M & 49M TX (OW22539CHAR-G27 and OW22539CHAR-G49TX)

R1 & R20 changed to 68K from 22K

R4 changed to 24K from 16K

R5 changed to 24K from 15K

R6 changed to 75K from 68K

The reason of this change is we need to modify the modulation timing for match the changed Rx IC RX3.

The old modulation timing is 400Hz and 2KHz, now is 250Hz and 1KHz.

Thanks & Best Regards