



Client: M/A-COM, Inc.
Model: M7100^(IP) VHF Mobile Radio
Standards: FCC Part 90/IC RSS-119
Report #: 2004231
Date: Dec. 20, 2004




PHOTOGRAPH 7: TRX SYN BOARD COMPONENT SIDE LOWER RIGHT

Client: M/A-COM, Inc.
Model: M7100^(IP) VHF Mobile Radio
Standards: FCC Part 90/IC RSS-119
Report #: 2004231
Date: Dec. 20, 2004




PHOTOGRAPH 8: TRX SYN BOARD COMPONENT SIDE UPPER LEFT

Client: M/A-COM, Inc.
Model: M7100^(IP) VHF Mobile Radio
Standards: FCC Part 90/IC RSS-119
Report #: 2004231
Date: Dec. 20, 2004



PHOTOGRAPH 9: TRX SYN BOARD COMPONENT SIDE UPPER RIGHT



PHOTOGRAPH 10: TRX SYN BOARD SOLDER SIDE COMPLETE VIEW