



Annex C

Out of Band Emissions


UPLINK_CDMA_1710 - 1755 MHz_high side




UPLINK_CDMA_1710 - 1755 MHz_low side




UPLINK_CDMA_1850 - 1910 MHz_high side




UPLINK_CDMA_1850 - 1910 MHz_low side



UPLINK_CDMA_704 - 716 MHz_high side




UPLINK_CDMA_704 - 716 MHz_low side






UPLINK_CDMA_776 - 787 MHz_high side




UPLINK_CDMA_776 - 787 MHz_low side






UPLINK_CDMA_824 - 849 MHz_high side




UPLINK_CDMA_824 - 849 MHz_low side







UPLINK_GSM_1710 - 1755 MHz_high side




UPLINK_GSM_1710 - 1755 MHz_low side



UPLINK_GSM_1850 - 1915 MHz_high side




UPLINK_GSM_1850 - 1915 MHz_low side






UPLINK_GSM_704 - 716 MHz_high side




UPLINK_GSM_704 - 716 MHz_low side






UPLINK_GSM_776 - 787 MHz_high side




UPLINK_GSM_776 - 787 MHz_low side







UPLINK_GSM_824 - 849 MHz_high side




UPLINK_GSM_824 - 849 MHz_low side




UPLINK_WCDMA_1710 - 1755 MHz_high side




UPLINK_WCDMA_1710 - 1755 MHz_low side




UPLINK_WCDMA_1850 - 1910 MHz_high side




UPLINK_WCDMA_1850 - 1910 MHz_low side




UPLINK_WCDMA_704 - 716 MHz_low side




UPLINK_WCDMA_704 - 716 MHz_high side




UPLINK_WCDMA_776 - 787 MHz_low side




UPLINK_WCDMA_776 - 787 MHz_high side



UPLINK_WCDMA_824 - 849 MHz_high side




UPLINK_WCDMA_824 - 849 MHz_low side







Downlink_CDMA_1930 - 1990 MHz_high side




Downlink_CDMA_1930 - 1990 MHz_low side



Downlink_CDMA_2110 - 2155 MHz_high side




Downlink_CDMA_2110 - 2155 MHz_low side






Downlink_CDMA_734 - 746 MHz_high side




Downlink_CDMA_734 - 746 MHz_low side






Downlink_CDMA_746 - 757 MHz_high side




Downlink_CDMA_746 - 757 MHz_low side







Downlink_CDMA_869 - 894 MHz_high side




Downlink_CDMA_869 - 894 MHz_low side




Downlink_GSM_1930 - 1990 MHz_high side




Downlink_GSM_1930 - 1990 MHz_low side



Downlink_GSM_2110 - 2155 MHz_high side




Downlink_GSM_2110 - 2155 MHz_low side






Downlink_GSM_734 - 746 MHz_high side




Downlink_GSM_734 - 746 MHz_low side







Downlink_GSM_746 - 757 MHz_high side




Downlink_GSM_746 - 757 MHz_low side




Downlink_GSM_869 - 894 MHz_high side




Downlink_GSM_869 - 894 MHz_low side




Downlink_WCDMA_1930 - 1990 MHz_high side




Downlink_WCDMA_1930 - 1990 MHz_low side




Downlink_WCDMA_2110 - 2155 MHz_high side




Downlink_WCDMA_2110 - 2155 MHz_low side



Downlink_WCDMA_734 - 746 MHz_high side




Downlink_WCDMA_734 - 746 MHz_low side







Downlink_WCDMA_746 - 757 MHz_high side



Downlink_WCDMA_746 - 757 MHz_low side



Downlink_WCDMA_869 - 894 MHz_high side



Downlink_WCDMA_869 - 894 MHz_low side

