

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

July 20, 2001

RE: Spin-Cast Inc.
FCC ID: OXHSCRC001

I have just a few brief comments on the Exhibits associated with this Application.

- 1.) The labeling for this device does not conform to the requirements of 15.19. If the device is smaller than the palm of the hand, the two-part statement of 15.19(a)(3) may appear in the manual. Please resubmit corrected Exhibits.
- 2.) The internal photographs are of insufficient detail. Please submit full sized photos of both sides of printed wiring board with all RF shielding removed. Submit just one to a page of sufficient quality to distinguish the individual components on the board. Orthographic views are preferred.
- 3.) Am not certain if additional information could be derived from better external photos, but clearer ones might be helpful.

That's it. Get me these updated Exhibits and your Grant will be issued.

Bill



William H. Graff
Examining Engineer
President and Director of Engineering
<mailto:whgraff@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.