



SerComm Corporation 中磊電子股份有限公司

Taipei Office: 8F, No.3-1, YuanQu St., NanKang, Taipei 115, Taiwan, R.O.C.

TEL: 886-2-2655-3988

FAX: 886-2-2655-3966

Chu Nan Office: 3F, No. 81, YuYi Rd., Chu-Nan, Miao-Li 350, Taiwan, R.O.C.

TEL: 886-37-585-899

FAX: 886-37-585-000

Date: December 8, 2011

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

c.c.
Compliance Certification Services
Certification Division
47173 Benicia Street
Fremont, CA 94538, USA

FCC ID: P27-WAP321

To whom it may concern:

IEEE 802.11b or 802.11g operation of this product in the U.S.A. is firmware-limited to channels 1 through 11.
IEEE 802.11b or 802.11g operation of this product in the Canada is firmware-limited to channels 1 through 11.


For UNII:

IEEE 802.11a operation of this product in the U.S.A. is firmware-limited to channels 36 through 48.
IEEE 802.11a operation of this product in the Canada is firmware-limited to channels 36 through 48.

For DTS:

IEEE 802.11a operation of this product in the U.S.A. is firmware-limited to channels 149 through 165.
IEEE 802.11a operation of this product in the Canada is firmware-limited to channels 149 through 165.

Yours sincerely,



數位簽署者: Ronnie Cheng
DN: cn=Ronnie Cheng,
email=ronnie_cheng@sercomm.
com, o=SerComm Corporation,
ou=RD Division, c=TW - 台灣
日期: 2011.12.07 18:29:54
+08'00'

Ronnie Cheng
Associate Manager / R&D Division
SerComm Corporation
TEL: 886-2-2655-3988 #2547
FAX: 886-2-2655-3975
E-Mail: ronnie_cheng@sercomm.com