

Marianne Bosley

To: alice_wong@hkstc.com

Subject: Audex Technology

Hi Alice,

There has been a discrepancy uncovered by Chris Harvey when he got the application to grant.

The Test Report indicated 88.7MHz operation only.

The Users Manual indicates that 88-108MHz is available.

You must either give a new manual to reflect 88.7 MHz, or give additional data so that the test report will reflect 88-108 MHz.

I must put this in a hold status until we clear this up. Sorry. Any questions, let me know.

Regards,

Marianne

Marianne T. Bosley

EMC Administrator

410-354-3300 X 412

mbosley@metlabs.com