



CE 2200

Your Specialist in Loss Prevention

P/N : WG APS RAD

S/N : 10/11 00001

INPUT : 24VAC 50/60Hz 0.5A


MFD : November 2010
Made in CHINA



Fuse replacement Build-in fuse
(time-delay fuse) 2mm x 6mm 0.5A

FCC ID : P9I-APSRAD

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS:(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.



LABEL LOCATION