



October 17, 2006

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Ref.: FCC ID: PBWB187R26H
MODEL: VOIP8411B/37

To Whom It May Concern:

This submittal will serve as a Class II Permissive Change approval for the above-mentioned FCC Identifier.

The differences between the originally approved radio and the modified radio is as follows:

The handset unit has been modified to have an external metallic grille on the receiver at the front and on the handsfree speaker at the rear.

We have performed radiated emissions testing and there is no degradation from the original test data and there is no change in the output power. The data in the test report shows that it still continues to meet the FCC requirements for this class of equipment.

SAR testing was also performed on this model and a SAR report is included.

Should you have any questions or require any further information, please advise.

Regards,

Mario R. de Aranzeta, CE.T.
Engineer

849 NW State Road 45 • P. O. Box 370 • Newberry, Florida 32669 USA
Telephone (352) 472-5500 • (888) 472-2424 • FAX (352) 472-2030 • email:
info@timcoengr.com