

14085 Howard Rd  
Dayton, MD 21036

# TRP/Cetecom bvba

October 22, 2001

Federal Communications Commission  
7435 Oakland Mills Rd  
Columbia, MD 21036

Re: Pending Application for Ericsson PCS phone

Gentlemen:

Ericsson wishes to modify the FCC ID for the pending application. This application was filed under FCC ID: PBY6130202. Ericsson wishes to modify the FCC ID to read as follows: FCCID:PBY6130201-BV. A revised label has been submitted as an attachment to the file.

Sincerely,

Phillip Inglis  
Consultant