


WLAN label is stuck on the **core side** of D cover.



## 9462NGW Label & Location



FCC ID: PD99462NG  
IC: 1000M-9462NG