


Appendix C – SAR Test Setup Photos



Test Position Laptop AL 0 mm Gap

Note: All cables removed prior to testing.



Test Position Laptop CF 0 mm Gap

Note: All cables removed prior to testing.



Front of Device Laptop Mode AL



Front of Device Laptop Mode CF