


Location and Separation Distances Notebook Mode Diagrams



Appendix C – SAR Test Setup Photos



Test Position Laptop 0 mm Gap

Note: All cables removed prior to testing.



Laptop Mode