


WLAN label is stuck on the **core side** of D cover.



Module AX201NGW

