

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All cables are removed prior to testing.




Test Position Top 0 mm Gap

Note: All cables are removed prior to testing.



Front of Device



Back of Device