


KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0019
Page (82) of (88)



Appendix C. #Antenna Location & Distance



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0019
Page (83) of (88)

**Appendix D. EUT Photo****Notebook Mode Front View**


KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0019
Page (84) of (88)



Tablet Mode_Front



Tablet Mode_Rear




Tablet Mode_Left**Tablet Mode_Right**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0019
Page (86) of (88)

**Tablet Mode_Top****Tablet Mode_Bottom**

Appendix E. Test Setup Photo**Notebook Mode_Rear (0 mm)****Tablet Mode_Left (0 mm)**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR21-SPF0019
Page (88) of (88)

**Tablet Mode_Right (0 mm)****End of test report**

This test report shall not be reproduced, except in full, without the written approval
KCTL-TIA002-004/4

KP21-01680