

CORRECTION TO TEST REPORT:

DTL1_FCC.DOC

ERROR

The values in first table in test report section 6.6.2 are not correct.

CORRECTION

The correct values are copied from the calculation table to the value table.

The corrected page replaces the old one.


6.6.2 Limits and results

Peak output power

EUT Channel	Limit (W)	Test result (W)
2	≤ 1	0.00103
40		0.00115
80		0.00073

EUT channel	Measured value [dBm]	Cable attenuation [dB]	Power output [dBm]	Power output [W]
2	-0.08	0.2	0.12	0.00103
40	0.42	0.2	0.62	0.00115
80	-1.57	0.2	-1.37	0.00073

6.6.3 Screen shots



Picture 9. Peak output power on channel 2