

From: certadm [certadm@ccsemc.com]
To: leeyeee@ms7.hinet.net
Cc: mkuo@ccsemc.com
Subject: Colortac Technology, FCC ID:PDU15, Assessment no:AN00T1180

Notice_content

Dear Leon:

Question #1: From the EUT Internal photos, there are a lots of copper tapes were used to modify the device. These modifications are questionable to be able to implement into the production unit. Please provide a modification report with detail description on how the modifications will incorporated into the final product unit. Please make sure you address internal photos Figure 9,10,11,12,16,18,19,20 and 24.

The items

indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.