



Report No.: 01116351
Mode: Talk
Model: 39238

Tested By: Hong, Report No.: 01116351


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 01116351
Mode: Talk
Model: 39238

Tested By: Hong, Report No.: 01116351

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB
Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
12.30000	42.8	48.0
24.62000	27.6	48.0

* limit exceeded



Report No.: 01116351
Mode: Talk
Model: 39233

Tested By: Hong, Report No.: 01116351

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 01116351
Mode: Talk
Model: 39233

Tested By: Hong, Report No.: 01116351

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency QP Level QP Limit

MHz dBuV dBuV

28.00000	28.9	48.0
----------	------	------

* limit exceeded

Ctrl No.: N/A