

Inside view of EUT




Top side view of main board



Bottom side view of main board




View of cable tuner #1, #2



Report no. ETLT171102.0134, Page D4 of D6

Inside view of cable tuner #1, #2



View of cable tuner #3

