

# Airspan Networks Inc.

777 Yamato Rd Suite 310, Boca Raton, Florida, United States, 33431

## FCC DECLARATION LETTER

**FCC ID: PIDCRM3650**

Date: 2013.02.17

To whom it may concern:

By **CRM 3.65GHz** hardware configuration, the ratios of DL: UL are: (31:16), (29:18), (26:21), (23:24) and (14:33). That means it can not support the higher ratio then (31:16), meaning 31 downlink symbols and 16 uplink symbols. The ratio can not be modified to higher ratio then (31:16) by any method. The device does not support mobile station FDD mode.

Sincerely,



---

**Brian Roberts**

Engineering Dept.  
Airspan Networks Inc.  
Tel: +1 561 893 8686  
Fax: +1 561 893 8671  
e-mail: zlevi@airspan.com