

INTERTEK TESTING SERVICES


Report No.: HK08091468-1
Model No.: 9336B
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



*RBW 1 kHz Delta 1 [T1]
*VBW 3 MHz -46.07 dB
Ref 0 dBm Att 30 dB SWT 100 ms 50.800000000 kHz

1 PK
VIEW



Tested By: (Michael Leng)

Date: 10/10/08

Checked By: (Ben Lo)

Date: 28/10/08

Test Result: Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08091468-1

Model No.: 9336B


Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



*RBW 1 kHz Delta 1 [T1]
 *VBW 3 MHz -44.38 dB
 Ref 0 dBm Att 30 dB SWT 100 ms -49.200000000 kHz

1 PR
VIEW



Tested By: Michael Leung
 (Michael Leung)

Date: 10/10/08

Checked By: Ben W
 (Ben W)

Date: 28/10/08

Test Result: Pass / Fail / NA

Report No.: HK08091468-1

Model No.: 9336B


Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



*RBW 1 kHz Delta 1 [T1]
 *VBW 3 MHz -44.20 dB
 Ref 0 dBm Att 30 dB SWT 100 ms -49.400000000 kHz

1 PK
 VIEW



Tested By: Michael Long
 (Michael Long)

Date: 10/10/08

Checked By: Ben
 (Ben)

Date: 28/12/08

Test Result: Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08091468-1

Model No.: 9336B


Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



*RBW 1 kHz Delta 1 [T1]
 *VBW 3 MHz -44.50 dB
 Ref 0 dBm Att 30 dB SWT 100 ms 51.400000000 kHz

1 PK
 VIEW



Tested By: Michael Leung
 (Michael Leung)

Date: 10/10/08

Checked By: Ben
 (Ben)

Date: 28/10/08

Test Result: Pass / Fail / NA