

INTERTEK TESTING SERVICES


Report No.: HK08091468-1
Model No.: 9336B
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 10 dBm Att 40 dB RBW 3 MHz Delta 1 [T1]
*VBW 3 MHz -0.00 dB
SWT 50 ms 16.400000 ms

1 AP
CLRWR



Tested By: Michael Leung
(Michael Leung)

Date: 10/10/08

Checked By: Ben U
(Ben U)

Date: 28/10/08

Test Result: Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08091468-1

Model No.: 9336B


Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



RBW 3 MHz Delta 1 [T1]
 *VBW 3 MHz 0.27 dB
 Ref 10 dBm Att 40 dB SWT 20 ms 16.420000 ms

1 AP
 CLRWR



Tested By : *(Signature)*
 (Michael Leung)

Date : 10/10/08

Checked By : *(Signature)*
 (Ben Ho)

Date : 28/10/08

Test Result : Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08091468-1
Model No.: 9336B
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement




RBW 3 MHz Delta 1 [T1]
*VBW 3 MHz 2.58 dB
SWT 20 ms 1.340000 ms

Ref 10 dBm

Att 40 dB

1 AP
CLRWR



Center 49.86 MHz

2 ms/

Tested By: Michael Leary
(Michael Leary)

Date: 10/10/08

Checked By: Ben
(Ben)

Date: 28/10/08

Test Result: Pass / Fail / NA


Report No.: HK08091468-1
Model No.: 9336B
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 10 dBm Att 40 dB RBW 3 MHz Delta 1 [T1]
*VBW 3 MHz 3.97 dB
SWT 20 ms 460.000000 μ s

1 AP
CLRWR



Tested By: Michael Leung
(Michael Leung)

Date: 10/10/08

Checked By: Ben Ho
(Ben Ho)

Date: 28/10/08

Test Result: Pass / Fail / NA