

Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]
Sent: Wednesday, April 03, 2002 4:27 PM
To: kyle@celectronics.com
Subject: FCC ID: PMHFMS2000



Scott McCutchan.vcf

In order for processing of this application (FCC ID: PMHFMS2000) to continue, the following issue(s) will have to be addressed:

- 1) The FCC ID label is not in compliance with section 2.915 of the FCC rules. It should be: FCC ID: PMHFMS2000, not FCC ID #PMHFMS2000. Please submit a corrected label.
- 2) According to the data sheets in the test report, the fundamental emission was averaged. A Quasi-Peak detector should be used at this frequency.

Correpondence to this request may be submitted on our web site under confirmation number PMHFMS2000-1.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to scott@celectronics.com.

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>