




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


APPENDIX E: INTERNAL PHOTOGRAPHS



PHOTOGRAPH 5: LCD BOARD FRONT WITH CIRCUITS FOLDED DOWN




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 6: LCD BOARD FRONT WITH LCD CIRCUITS FOLDED UP




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 7: LCD BOARD REAR WITH SHIELDS




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 8: LCD BOARD WITH OUT SHIELDS.JPEG LCD BOARD WITH OUT SHIELDS




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 9: KEYBOARD FRONT




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 10: KEYBOARD REAR



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 11: REAR COVER INSIDE