

*April 10, 2006*

*Bandai (HK) Company Limited  
Rm. 2902, United Ctr.,  
95 Queensway,  
Hong Kong.  
Tel. : 28660229  
Fax. : 25271971*

*Dear Thomas Wong:*

*Enclosed you will find your file copy of a Part 15 Certification (FCC ID: PQ391442).  
We have forwarded the original to ITS-NA Inc. for review.*

*For your reference, review normally take 3 weeks. Approval will then be granted  
when no query is sorted.*

*Please contact me if you have any questions regarding the enclosed material.*

*Sincerely,*



*Billy Chow  
Assistant Manager*

*Enclosure*

FCC ID: PQ391442

*April 10, 2006*

*Federal Communications Commission  
c/o Mellon Bank  
Three Mellon Bank  
525 William Penn Way  
27th Floor, Room 153-2713  
Pittsburgh, PA 15251-5315  
Attn: Wholesale Lockbox Shift Supervisor*

*To The Federal Communications Commission:*

*Enclosed you will find an original Part 15 Application for Certification for Bandai (HK) Company Limited (FCC ID:PQ391442).*

*Also enclosed you will find a check in the amount of US\$300 to cover the application fee.*

*Please contact me if you have any questions regarding the enclosed material.*

*Sincerely,*



*Billy Chow  
Assistant Manager*

*BC  
Enclosure*

FCC ID: PQ391442

**Bandai (HK) Company Limited**

Application

For

Certification

(Change of identification)

Power Ranger R/C Cycle

**(FCC ID: PQ391442)**

WO# 0605880

BC/at

April 10, 2006

- The test results reported in this report shall refer only to the sample actually tested and shall not refer or be deemed to refer to bulk from which such a sample may be said to have been obtained.
- This report shall not be reproduced except in full without prior authorization from Intertek Testing Services Limited

FCC ID: PQ391442

---

## INTERTEK TESTING SERVICES

---

### LIST OF EXHIBITS

#### *INTRODUCTION*

|                   |                                                      |
|-------------------|------------------------------------------------------|
| <i>EXHIBIT 1:</i> | General Description                                  |
| <i>EXHIBIT 2:</i> | Original Certificate Copy                            |
| <i>EXHIBIT 3:</i> | Authorization Letter of the Change of Identification |
| <i>EXHIBIT 4:</i> | Equipment Photographs                                |
| <i>EXHIBIT 5:</i> | Product Labelling                                    |
| <i>EXHIBIT 6:</i> | Instruction Manual                                   |

---

## INTERTEK TESTING SERVICES

---

### Table of Contents

|                                                                               |    |
|-------------------------------------------------------------------------------|----|
| 1.0 <b><u>General Description</u></b> .....                                   | 2  |
| 1.1 Product Description .....                                                 | 4  |
| 1.2 Original Identification Information .....                                 | 3  |
| 1.3 Reason of Change in Identification .....                                  | 3  |
| 1.4 Representative of Previous Field Data .....                               | 3  |
| 2.0 <b><u>Original Certification Copy</u></b> .....                           | 6  |
| 3.0 <b><u>Authorization Letter for the Change of Identification</u></b> ..... | 7  |
| 4.0 <b><u>Equipment Photographs</u></b> .....                                 | 9  |
| 5.0 <b><u>Product Labelling</u></b> .....                                     | 11 |
| 6.0 <b><u>Instruction Manual</u></b> .....                                    | 13 |

---

## **INTERTEK TESTING SERVICES**

---

### **EXHIBIT 1**

### **GENERAL DESCRIPTION**

## INTERTEK TESTING SERVICES

---

### 1.0 **General Description**

#### 1.1 Product Description

The equipment under test (EUT) is a transmitter for a RC Cycle operating at 27.145 MHz which is controlled by a crystal. The EUT is powered by a 9V battery. The EUT has an ON/OFF switch and a control wheel. After switched ON the EUT, the control wheel is used to control the RC Cycle moving forward and backward with clockwise direction.

## INTERTEK TESTING SERVICES

---

### 1.2 Original Identification Information

The original identification (FCC ID) of the equipment is PQ391441 and granted on September 15, 2005. The name of grantee is Bandai (HK) Company Limited. The copy of certificate is attached in Exhibit 2.

### 1.3 Reason of Change in Identification

The reason of change in Identification by the original grantee, Bandai (HK) Company Limited and the authorization letter are attached in Exhibit 3. The equipment of this new application is electrically identical to the old application.

### 1.4 Representative of Previous Field Data

The data of the equipment previous filed with FCC ID: PQ391441 by commission continues to be representative and applicable to the equipment bearing the changed identification.

All the items listed under this filing are confirmed by:

*Billy Chow*  
*Assistant Manger*  
*Intertek Testing Services*  
*Agent for Bandai (HK) Company Limited*



\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date

---

**INTERTEK TESTING SERVICES**

---

**EXHIBIT 2**

**ORIGINAL CERTIFICATE COPY**

---

**INTERTEK TESTING SERVICES**

---

**EXHIBIT 3**

**AUTHORIZATION LETTER FOR THE CHANGE OF IDENTIFICATION**

---

**INTERTEK TESTING SERVICES**

---

**EXHIBIT 4**

**EQUIPMENT PHOTOGRAPHS**

## INTERTEK TESTING SERVICES

---

### 4.0 Equipment Photographs

Photographs of the tested EUT are attached.

---

**INTERTEK TESTING SERVICES**

---

**EXHIBIT 5**

**PRODUCT LABELLING**

## INTERTEK TESTING SERVICES

---

### 5.0 **Product Labelling**

For electronic filing, the FCC ID label artwork and the label location are saved with filename: label.pdf

---

**INTERTEK TESTING SERVICES**

---

**EXHIBIT 6**

**INSTRUCTION MANUAL**

## INTERTEK TESTING SERVICES

---

### 6.0 **Instruction Manual**

For electronic filing, a preliminary copy of the Instruction Manual is saved with filename: manual.pdf