



Solder side view of Power board


Report no. ETLE051219.016, Page 6 of 10

Appendix D. Internal Photographs



Component side view of Front Board



Solder side view of Front Board




Inside View of The EUT of RF Modulator



Component side view RF Modulator




View of Front Cover



Appendix D. Internal Photographs

View of Bottom cover



View of Top cover

