

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1





Photo 2

Worst Case Position

Below 30MHz (Controller: X-axis / Antenna: X-axis)

Above 30MHz (Antenna: Horizontal: X-axis, Vertical: X-axis)


X-axis



Y-axis



Z-axis



UL Japan, Inc.


Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

Worst case position



Mechanical Key (Inserted)



Mechanical Key (Not Inserted) Worst

End of Report