



Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_c.jpg cB-RWE241, internal view


Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_m.jpg

cB-RWE241, main PCB, top view


Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_k.jpg

cB-RWE241, main PCB, bottom view

Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_l.jpg


cB-RWE241, main PCB, bottom view, antenna desoldered

Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_f.jpg cB-0926-02, top view


Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_n.jpg

cB-0926-02, top view, shielding removed

Annex C of test report F101042E2
EUT: cB-0926-02 inside cB-RWE241
Manufacturer: connectBlue AB



101042_g.jpg cB-0926-02, bottom view