

WILSON ELECTRONICS, LLC
3301 E. Deseret Dr, St. George, UT 84790
T. 1800 204 4104 F. 1 435 673 0899 E. info@weboost.com
www.weboost.com www.wilsonpro.com

June 13, 2025

To: Whom It May Concern

Alternative Warning Label Placement

This letter is to request alternative warning label placement for the signal booster model number 470082. The signal booster is too small to fit the warning label as can be seen from the Label Placement and External Photos Exhibits. Instead, the warning can be found on page 13 of the User Manual.

Sincerely,

Ilesh Patel

Senior Engineering Product Manager