




Annex D


Conducted Spurious Emission



Port 1_Downlink_1930 - 1990 MHz_plot 1




Port 1_Downlink_1930 - 1990 MHz_plot 2






Port 1_Downlink_2110 - 2155 MHz_plot 1




Port 1_Downlink_2110 - 2155 MHz_plot 2






Port 1_Downlink_728 - 746 MHz_plot 1




Port 1_Downlink_728 - 746 MHz_plot 2






Port 1_Downlink_746 - 757 MHz_plot 1




Port 1_Downlink_746 - 757 MHz_plot 2






Port 1_Downlink_869 - 894 MHz_plot 1




Port 1_Downlink_869 - 894 MHz_plot 2






Port 2_Downlink_1930 - 1990 MHz_plot 1




Port 2_Downlink_1930 - 1990 MHz_plot 2






Port 2_Downlink_2110 - 2155 MHz_plot 1




Port 2_Downlink_2110 - 2155 MHz_plot 2






Port 2_Downlink_728 - 746 MHz_plot 1




Port 2_Downlink_728 - 746 MHz_plot 2






Port 2_Downlink_746 - 757 MHz_plot 1




Port 2_Downlink_746 - 757 MHz_plot 2






Port 2_Downlink_869 - 894 MHz_plot 1




Port 2_Downlink_869 - 894 MHz_plot 2






Port 3_Downlink_1930 - 1990 MHz_plot 1




Port 3_Downlink_1930 - 1990 MHz_plot 2






Port 3_Downlink_2110 - 2155 MHz_plot 1




Port 3_Downlink_2110 - 2155 MHz_plot 2






Port 3_Downlink_728 - 746 MHz_plot 1




Port 3_Downlink_728 - 746 MHz_plot 2






Port 3_Downlink_746 - 757 MHz_plot 1




Port 3_Downlink_746 - 757 MHz_plot 2






Port 3_Downlink_869 - 894 MHz_plot 1




Port 3_Downlink_869 - 894 MHz_plot 2






Port 4_Downlink_1930 - 1990 MHz_plot 1




Port 4_Downlink_1930 - 1990 MHz_plot 2






Port 4_Downlink_2110 - 2155 MHz_plot 1




Port 4_Downlink_2110 - 2155 MHz_plot 2






Port 4_Downlink_728 - 746 MHz_plot 1




Port 4_Downlink_728 - 746 MHz_plot 2






Port 4_Downlink_746 - 757 MHz_plot 1




Port 4_Downlink_746 - 757 MHz_plot 2






Port 4_Downlink_869 - 894 MHz_plot 1




Port 4_Downlink_869 - 894 MHz_plot 2






Uplink_1710 - 1755 MHz_plot 1




Uplink_1710 - 1755 MHz_plot 2






Uplink_1850 - 1910 MHz_plot 1




Uplink_1850 - 1910 MHz_plot 2






Uplink_698 - 716 MHz_plot 1




Uplink_698 - 716 MHz_plot 2






Uplink_776 - 787 MHz_plot 1




Uplink_776 - 787 MHz_plot 2






Uplink_824 - 849 MHz_plot 1




Uplink_824 - 849 MHz_plot 2






Downlink_746 - 757 MHz_ extra test 1559 - 1610_RBW 1 MHz




Downlink_746 - 757 MHz_ extra test 1559 - 1610_RBW 10 kHz






Downlink_746 - 757 MHz_ extra test 763 - 775




Downlink_746 - 757 MHz_ extra test 793 - 805






Uplink_776 - 787 MHz_ extra test 1559 - 1610_RBW 1 MHz




Uplink_776 - 787 MHz_ extra test 1559 - 1610_RBW 10 kHz





UPlink_776 - 787 MHz_ extra test 763 - 775



UPlink_776 - 787 MHz_ extra test 793 - 805

