




Annex H

Occupied Bandwidth




Dedicated Ports

OCC BW_CDMA_UL Input_1732.5 MHz




OCC BW_CDMA_UL Input_1882.5 MHz






OCC BW_CDMA_UL Input_707 MHz




OCC BW_CDMA_UL Input_781.5 MHz






OCC BW_CDMA_UL Input_836.5 MHz




OCC BW_CDMA_UL Output_1732.5 MHz






OCC BW_CDMA_UL Output_1882.5 MHz




OCC BW_CDMA_UL Output_707 MHz






OCC BW_CDMA_UL Output_781.5 MHz




OCC BW_CDMA_UL Output_836.5 MHz






OCC BW_GSM_UL Input_1732.5 MHz




OCC BW_GSM_UL Input_1882.5 MHz






OCC BW_GSM_UL Input_707 MHz




OCC BW_GSM_UL Input_781.5 MHz






OCC BW_GSM_UL Input_836.5 MHz




OCC BW_GSM_UL Output_1732.5 MHz






OCC BW_GSM_UL Output_1882.5 MHz




OCC BW_GSM_UL Output_707 MHz






OCC BW_GSM_UL Output_781.5 MHz




OCC BW_GSM_UL Output_836.5 MHz






OCC BW_WCDMA_UL Input_1732.5 MHz




OCC BW_WCDMA_UL Input_1882.5 MHz






OCC BW_WCDMA_UL Input_707 MHz




OCC BW_WCDMA_UL Input_781.5 MHz






OCC BW_WCDMA_UL Input_836.5 MHz




OCC BW_WCDMA_UL Output_1732.5 MHz






OCC BW_WCDMA_UL Output_1882.5 MHz




OCC BW_WCDMA_UL Output_707 MHz






OCC BW_WCDMA_UL Output_781.5 MHz




OCC BW_WCDMA_UL Output_836.5 MHz






OCC BW_CDMA_DL Input_1962.5 MHz




OCC BW_CDMA_DL Input_2132.5 MHz






OCC BW_CDMA_DL Input_737 MHz




OCC BW_CDMA_DL Input_751.5 MHz






OCC BW_CDMA_DL Input_881.5 MHz




OCC BW_CDMA_DL Output_1962.5 MHz






OCC BW_CDMA_DL Output_2132.5 MHz




OCC BW_CDMA_DL Output_737 MHz






OCC BW_CDMA_DL Output_751.5 MHz




OCC BW_CDMA_DL Output_881.5 MHz






OCC BW_GSM_DL Input_1962.5 MHz




OCC BW_GSM_DL Input_2132.5 MHz






OCC BW_GSM_DL Input_737 MHz




OCC BW_GSM_DL Input_751.5 MHz






OCC BW_GSM_DL Input_881.5 MHz




OCC BW_GSM_DL Output_1962.5 MHz






OCC BW_GSM_DL Output_2132.5 MHz




OCC BW_GSM_DL Output_737 MHz






OCC BW_GSM_DL Output_751.5 MHz




OCC BW_GSM_DL Output_881.5 MHz






OCC BW_WCDMA_DL Input_1962.5 MHz




OCC BW_WCDMA_DL Input_2132.5 MHz






OCC BW_WCDMA_DL Input_737 MHz




OCC BW_WCDMA_DL Input_751.5 MHz






OCC BW_WCDMA_DL Input_881.5 MHz




OCC BW_WCDMA_DL Output_1962.5 MHz






OCC BW_WCDMA_DL Output_2132.5 MHz




OCC BW_WCDMA_DL Output_737 MHz






OCC BW_WCDMA_DL Output_751.5 MHz




OCC BW_WCDMA_DL Output_881.5 MHz






Common Ports

OCC BW_CDMA_UL Input_707 MHz




OCC BW_CDMA_UL Input_781.5 MHz






OCC BW_CDMA_UL Input_836.5 MHz




OCC BW_CDMA_UL Output_707 MHz






OCC BW_CDMA_UL Output_781.5 MHz




OCC BW_CDMA_UL Output_836.5 MHz






OCC BW_GSM_UL Input_707 MHz




OCC BW_GSM_UL Input_781.5 MHz






OCC BW_GSM_UL Input_836.5 MHz




OCC BW_GSM_UL Output_707 MHz






OCC BW_GSM_UL Output_781.5 MHz




OCC BW_GSM_UL Output_836.5 MHz






OCC BW_WCDMA_UL Input_707 MHz




OCC BW_WCDMA_UL Input_781.5 MHz






OCC BW_WCDMA_UL Input_836.5 MHz




OCC BW_WCDMA_UL Output_707 MHz






OCC BW_WCDMA_UL Output_781.5 MHz




OCC BW_WCDMA_UL Output_836.5 MHz






OCC BW_CDMA_UL Input_707 MHz




OCC BW_CDMA_UL Input_781.5 MHz






OCC BW_CDMA_UL Input_836.5 MHz




OCC BW_CDMA_UL Output_707 MHz






OCC BW_CDMA_UL Output_781.5 MHz




OCC BW_CDMA_UL Output_836.5 MHz






OCC BW_GSM_UL Input_707 MHz




OCC BW_GSM_UL Input_781.5 MHz






OCC BW_GSM_UL Input_836.5 MHz




OCC BW_GSM_UL Output_707 MHz






OCC BW_GSM_UL Output_781.5 MHz




OCC BW_GSM_UL Output_836.5 MHz






OCC BW_WCDMA_UL Input_707 MHz




OCC BW_WCDMA_UL Input_781.5 MHz






OCC BW_WCDMA_UL Input_836.5 MHz




OCC BW_WCDMA_UL Output_707 MHz





OCC BW_WCDMA_UL Output_781.5 MHz



OCC BW_WCDMA_UL Output_836.5 MHz

