




Annex I


Anti-Oscillation



of Restarts_B12 DL_728 - 746 MHz




of Restarts_B12 UL_698 - 716 MHz






of Restarts_B13 DL_746 - 757 MHz




of Restarts_B13 UL_776 - 787 MHz






of Restarts_B2 DL_1930 - 1995 MHz




of Restarts_B2 UL_1850 - 1915 MHz






of Restarts_B4 DL_2110 - 2155 MHz




of Restarts_B4 UL_1710 - 1755 MHz






of Restarts_B5 DL_869 - 894 MHz




of Restarts_B5 UL_824 - 849 MHz






Detection Time_B12 DL_728 - 746 MHz




Detection Time_B12 UL_698 - 716 MHz






Detection Time_B13 DL_746 - 757 MHz




Detection Time_B13 UL_776 - 787 MHz






Detection Time_B2 DL_1930 - 1995 MHz




Detection Time_B2 UL_1850 - 1915 MHz






Detection Time_B4 DL_2110 - 2155 MHz



Detection Time_B4 UL_1710 - 1755 MHz







Detection Time_B5 DL_869 - 894 MHz




Detection Time_B5 UL_824 - 849 MHz







Restart Time_B13 DL_746 - 757 MHz




Restart Time_B13 UL_776 - 787 MHz






Restart Time_B2 DL_1930 - 1995 MHz




Restart Time_B2 UL_1850 - 1915 MHz






Restart Time_B4 DL_2110 - 2155 MHz




Restart Time_B4 UL_1710 - 1755 MHz





Restart Time_B5 DL_869 - 894 MHz



Restart Time_B5 UL_824 - 849 MHz

