



Annex I

Anti-Oscillation


of restarts_B12 DL_728 - 746 MHz_p2040010




of restarts_B12 UL_698 - 716 MHz_p2040010




of restarts_B13 DL_746 - 757 MHz_p2040010




of restarts_B13 UL_776 - 787 MHz_p2040010




Detection Time_B12 DL_728 - 746 MHz_p2040010




Detection Time_B12 UL_698 - 716 MHz_p2040010




Detection Time_B13 DL_746 - 757 MHz_p2040010




Detection Time_B13 UL_776 - 787 MHz_p2040010




Restart Timing_B12 DL_728 - 746 MHz_p2040010



Restart Timing_B12 UL_698 - 716 MHz_p2040010



Restart Timing_B13 DL_746 - 757 MHz_p2040010



Restart Timing_B13 UL_776 - 787 MHz_p2040010

