

## Description of Permissive Change

This report is prepared for FCC class II permissive change. This report is issued as a supplementary report to the original BVADT report no. RF990302L10. The differences compared with original report are changing and adding the following items.

- Changing brand, model and housing.
- Changing adapter model from MU08A9075100-A2 to MU08A9075100-A1.
- Adding adapter (Model: AD810F22).