

Annex 2: Set-up photographs
to TEST REPORT
No.: 2-20798191b/11

According to:
FCC Regulations
Part 15.107 & 15.207
Part 15.225 & 15.209
IC Regulations
RSS-Gen Issue 3
RSS-310, Issue 2

for

Sony Ericsson Mobile Communications AB

Mobile Phone AAD-3880112-BV

FCC-ID: PY7A3880112-BV
IC: 4170B-A3880112

Laboratory Accreditation and Listings			
 D-PL-12047-01-01	 Reg. No.: 736496 MRA US-EU 0003	 Reg. No.: 3462D-1 3462D-2	 Reg. No.: R-2665, R-2666 C-2914, T-1967 G-301
 LAB CODE 20011130-00		 AUTHORIZED RF LABORATORY	
accredited according to DIN EN ISO/IEC 17025			
CETECOM GmbH Laboratory Radio Communications & Electromagnetic Compatibility Im Teelbruch 116 • 45219 Essen • Germany Registered in Essen, Germany, Reg. No.: HRB Essen 8984 Tel.: + 49 (0) 20 54 / 95 19-954 • Fax: + 49 (0) 20 54 / 95 19-964 E-mail: info@cetecom.com • Internet: www.cetecom.com			


Table of contents

PHOTOGRAPHS OF SET-UP	3
------------------------------------	----------


Photographs of set-up



Conducted emissions on AC-mains



Radiated magnetic field strength for frequencies below 30MHz



Radiated electric field strength for frequencies above 30MHz and below 1GHz



Measurements of frequency error inside climatic chamber