

Prepared (also subject responsible if other)

**BGGINRC Mats Hansson** 

BGGINRC

**DESCRIPTION** 

No.

BGGIN 06:363 Uen

ite Rev

2006-08-08 A

Reference

## PY7AF052051 hardware change description

In order to improve the radiated performance of PY7AF052051 in GSM 900 and 1800 bands the following modifications was made.

- The antenna connector was changed
- Grounding around antenna the connector has been improved.

Checked

Due to this SAR was increased while radiated RF power for GSM 850 and 1900 remained was the same as before.

Radiated performance for GSM 900 and 1800 was increased.

Bluetooth performance is not affected by the changes.

FCC part 22, part 24 and SAR testing has been done and reports submitted